



New employee wing entrance



New employee wing entrance



New employee wing entrance




New employee wing entrance

New lab footers poured getting ready to start constructing walls



New lab footers poured
getting ready to start
constructing walls






Lobby currently being used to store things.



Hallway just off lobby



Restrooms



New duct work



New duct work



New duct work one of the meeting rooms





Walls going up on the
large meeting room



Walls going up on the
large meeting room



Looking out the front of
the large meeting room
area



More walls going up in the meeting room area.



Meeting room currently
being used for storage.